

## March Blast Monitoring - 2017



Date of blast monitoring	Location	Overpressure Reading (dB)L	Ground Vibration peak particle velocity (PPV) (mm/s)	Comments
		EPA requirements: - Readings must not >125dB at any time - Overpressure level must not exceed 120dB for 95% of blasts over each reporting period (calendar month)	EPA Requirements: c) PPV must not >10mm/second at any time d) GPPV must not exceed 5mm/s for 95% of blasts over each reporting period (calendar month)	
29/03/2017	Wave 5a Cut 30	107.5	3.134	
29/03/2017	Wave 5a Cut 30	108.8	2.556	