February 2017 Noise Monitoring



Contractor	Date of noise monitoring	Time of Noise Monitoring	Location	Noise Monitoring Results						Comments
				Laeq	Lafmax	Lzpk	Lafmin	Laf10	Laf90	
FKG - Wave 3, Section 4	2/02/2017	13:39	DW1530	68.8	92.7	124.1	61.5	71.5	64.5	Complaint
FKG - Wave 3, Section 4	6/02/2017	10:42	DW1530	65.3	71.7	98.3	60.7	67	63.5	Complaint
FKG - Wave 3, Section 4	8/02/2017	11:05	DW1530	66.2	84.2	101.7	56.4	68	61.5	During works
FKG - Wave 3, Section 4	8/02/2017	14:22	DW1530	63.2	81.9	111.9	44.4	66.5	54	During works
FKG - Wave 3, Section 4	9/02/2017	16:14	DW1530	60.7	72.6	106.2	49.6	64	55	During works
FKG - Wave 3, Section 4	13/02/2017	21:33	DW1688	59.6	76.9	102.9	48.1	62	53	During works - EVENING
FKG - Wave 3, Section 4	15/02/2017	23:46	DW1688	59.3	78.9	107.2	51.9	62.5	54	During works - NIGHT
FKG - Wave 3, Section 4	15/02/2017	21:41	DW1688	58.3	78.5	106.2	49.5	62.5	52	During works - EVENING (shift 2 & 3 activities)
FKG - Wave 3, Section 4	15/02/2017	22:10	DW1688	59.5	77.5	104.2	49.9	63.5	51.5	During works - NIGHT
SWC - Section 3	19/02/2017	10:08	#813 - Tyndale, Highway haulage entry / exit	62.2	71.6		44.4			Pacific Highway traffic dominant Nosie source. Sunday servicing crusher no Nosie impacts
SWC - Section 3	19/02/2017	9:46	#813 - Tyndale, Between Highway / Carpark	55.4	64.9		43.8			Pacific Highway traffic dominant Nosie source. Sunday servicing crusher no Nosie impacts
Pacifico Harwood - Portion E	27/02/2017	12:53pm	19 James Creek Road (R1256)	49.243773	72		39			Below NML 55dB(A) No construction works occuring. Dominant Noise source was existing Highway Traffic.
Pacifico Harwood - Portion E	27/02/2017	1:25pm	40 Morpeth Street (R1396)	50.840579	68.7		41.7			Below NML 55dB(A) No construction works occuring. Dominant Noise source was School and existing highway.
Pacifico Harwood - Portion E	27/02/2017	1:56pm	8 Martin Road (R1283)	58.641176	83.3		43.9			Above NML 55dB(A) however Mulcher operating as part of RMS bridge maintenance works. No construction works occuring. Dominant Noise source was RMS works occuring on existing Harwood Bridge.
Pacifico Harwood - Portion E	27/02/2017	2:18pm	1 Petticoat Lane (R1331)	51.28	69.2		39.3			Below NML 55dB(A). No construction works occuring. Dominant Noise source was loud TV from inside Dwelling and Rooster in adjacent yard.