



Contact: Karl Fetterplace
Phone: 9274 6263
Email: karl.fetterplace@planning.nsw.gov.au

Mr Stuart Hodgson
Principal Manager
Program Sustainability Environment & Planning
Sydney Metro, Transport for NSW
PO Box 588
North Ryde BC NSW 1670

Our ref: SSI 15_7400

Dear Mr Hodgson

Sydney Metro City & Southwest Chatswood to Sydenham (SSI 15_7400): Approval of the Early and Enabling Works (Sydney Yard Access Bridge) Construction Environmental Management Plan and sub-plans

I refer to your submission of the Construction Environmental Management Plan (CEMP), Construction Noise & Vibration Management sub-plan (CNVMP), Construction Noise and Vibration Monitoring Plan and Construction Heritage Management sub-plan for the Sydney Yard Access Bridge component of the Early and Enabling Works under conditions C8 and C13. I also note further revisions to these documents, responding to the Department's detailed comments and requirements.

The Department has reviewed the updated CEMP and other above-listed documents, and considers that they satisfactorily address the requirements of conditions C8 and C13, subject to the requirements and updates set out in **Attachment A**.

Given that Registered Aboriginal Parties (RAPs) were not consulted during the preparation of the CHMP, this approval is conditional on the basis that only works deemed by the Excavation Director as suitable to be managed by the Unexpected Finds Procedure will be undertaken during the remainder of the consultation period with the RAPs. The RAPs should be invited to be present on site during excavation.

On this basis, in accordance with conditions C8 and C13, I approve the following documents subject to the matters in **Attachment A** being satisfactorily addressed:

Management Plan/sub-plan	Condition
<i>Construction Environmental Management Plan (Rev 04 dated 6 June 2017)</i>	C8
<i>Construction Noise and Vibration Management sub-plan (Version V.06 dated 8 June 2017), incorporating Construction Noise and Vibration Monitoring Program</i>	C8, C13
<i>Construction Heritage Management sub-plan (Rev 04 dated 31 May 2017)</i>	C8


Please ensure that a final copy of all updated plans is provided to the Department for information, and all plans are made available at site and uploaded to the project's website.

You are also reminded that if there is any inconsistency between the approved plans and the conditions of the approval, then the requirements of the conditions of approval will prevail.

You are further reminded that in accordance with condition C15, the approved Construction Noise and Vibration Monitoring Program must be implemented for the duration of construction and for any longer period set out in the monitoring program or specified by the Secretary, whichever is the greater.

If you have any further queries or require clarification on this matter, please contact Karl Fetterplace, Senior Planner - Infrastructure Management on 9274 6263 or by email karl.fetterplace@planning.nsw.gov.au.

Yours sincerely

 9/6/17
Stacy Warren
Director
Infrastructure Management
as delegate of the Secretary

Attachment A – requirements of approval

1. Construction Environmental Management Plan (CEMP)

- Please ensure all references to a Traffic Management sub-plan are clarified to state that the reference is to a Construction Traffic Management Plan, as referred to in condition E82.
- Please ensure that the CEMP is updated to reflect required updates for the sub-plans, as far as relevant.

2. Construction Noise and Vibration Management Plan (CNVMP) and Noise and Vibration Construction Monitoring Program.

- Please update the Compliance Matrix to remove reference to “submitted by Sydney Metro” from condition C11. Section 8 includes the Noise and Vibration Monitoring Plan, to which the condition refers.
- Condition C11 requires the Construction Monitoring Program to include real-time monitoring, and for this real-time data to be available to the construction team, the Proponent, ER and AA. The Department and EPA must also be provided with access to the data. Please update this plan to commit to providing real time data within this Construction Monitoring Program.
- Please update the Construction Monitoring Program to state that the Construction Monitoring Report will be provided to the Department and relevant regulatory agencies (i.e. EPA and the City of Sydney Council) for information in accordance with condition C16.

3. Construction Heritage Management Plan (CHMP)

- Please either include REMM NAH4 or explain why this mitigation measure is not applicable to the SYAB works.
- Update the CHMP Compliance Matrix to address the requirements of the conditions and the following comments (as previously advised on 29 May 2017):
 - The Compliance Matrix states that REMMs NAH6, NAH7 and NAH10 would be completed outside the management of this CHMP. However, the Compliance Matrix also states that these mitigation measures are addressed in Table 4-2 Design Management. In response, it is stated that this statement has been deleted for clarity. It is assumed that this is a reference to Table 4-2, however, please confirm which statement has been deleted.
 - The Compliance Matrix references section 5.2 as containing information regarding REMM NAH3. However, section 5.2 is not a valid reference. It has been stated that the Compliance Matrix has been updated to state that the correct reference is to Table 5 – Incident Response. This reference needs to be confirmed in an updated Compliance Matrix, as table 4.1 appears to address this issue.
 - Please update Compliance Matrix to reference S 1.4 (Consultation) as relevant in addressing Condition C3(g).
 - Please update Compliance Matrix to reference S 1.3 as relevant to Condition E10.
 - Please update Compliance Matrix to reference Table 4-2 (Archival recording) as the relevant section of the CHMP that addresses Condition E13, not Table 4-2 (Archaeological reporting).
 - Please update Compliance Matrix to reference Table 4-2 (Nomination of an Excavation Director) as relevant to Condition E18.
 - Please update Compliance Matrix, Condition E20 to reference Table 4-2, not Table 4.2.

- Please update Compliance Matrix to include S 1.3 as a reference for Condition E26.
- Please update Compliance Matrix regarding the Exhumation Management Plan as S 5.2 isn't a valid section in the CHMP.
- Please update CEMF Compliance Matrix to reference all 11 Heritage Management measures as outlined in S 10.2 of the CEMF.
- Please update letter ordering of CEMF Compliance Matrix Heritage Management Interpretation. Please also ensure that Table 4-1 is referenced correctly throughout the CHMP Cover Sheet, instead of Table 4.1.