

Noise Monitoring - Parramatta Turnback Project - WE08 - 20-21 August 2016

| Monitoring Location | Date | Time (24Hr) & Duration (minutes) | Construction Activities | Standard or Out-of-Hour Works (Day/Evening/Night) | Weather Conditions | In Response to Complaint? | RBL (dBA) - from EIA Checklist | Noise Goal (RBL + 5dBA) | Predicted Levels | Recorded Noise Level LAeq (15 min) (dBA) | Recorded Noise Level LAmx (dBA) | Recorded Noise Level LAmin (dBA) | Recorded Noise Level LA10 (dBA) | Recorded Noise Level L90 (dBA) | Compliance | Person Carrying Out Noise Monitoring | Comments |
|---|------------|----------------------------------|---|---|--------------------|---------------------------|--------------------------------|-------------------------|------------------|--|---------------------------------|----------------------------------|---------------------------------|--------------------------------|------------|--------------------------------------|--|
| Marion St | 20/08/2016 | 08:00 to 08:15 | Harris Park Car Park Site compound, material loading and unloading, generator running | OOHW Day | Clear | No | 48 | 53 | 54.4 | 54.4 | 70 | 46 | 59 | 49 | Yes | Charissa Pillay | Traffic on nearby street, generator and excavator in the site compound audible |
| Residential block facing the rail corridor (city end) | 20/08/2016 | 09:51 to 10:11 | Grinding and plant movement | OOHW Day | Clear | No | 48 | 53 | 66.6 | 66 | 83 | 58 | 80 | 53 | Yes | Charissa Pillay | Traffic on nearby street |