

WE31 Noise Monitoring Results - 26 January - 1 February - Wickham Transport Interchange (SIG19)

NovoRail Reference Number	Site #	Monitoring Location	Weather Conditions	Date	Time	Duration	Time Units	Construction Activities	Main source of noise	LA(eq)	LA(10)	LA(90)	LA(max)	LA(min)	Shift	Audible noise from WTI construction activities	Predicted construction sound pressure level (LA(eq,15min))	Compliance	Comments
1	NCA 5	59 Station Street, Wickham	Wind ~ 30km/h	29/01/2015	20:17	15	Mins	Lighting towers	Trains idling	60.2	61.7	57.5	71.6	56.8	Evening	Lighting towers	42	Y	Major source of noise from train idling. Additional noise from local traffic, noise from wind in trees, banging of flag pole rope and birds. Minimal additional noise from lighting towers.

** higher than predicted noise levels due to non-construction related activities i.e. traffic*