

Water Discharge to Land Monitoring - March 2017

Monitoring Location: POINT 2 - Land Irrigation Areas

Wave/Portion	Contractor	Basin Name/ Number	Date of Discharge	Volume of Discharge (kL)	EPL water quality parameters		Comments
					Oil & Grease	pH	
					Nil	6.8 – 8.5	
Portion E	Pacifico Harwood	Sediment Basin 1	3/03/2017	300kL	Nil	8.1	Land Irrigation area approved . Irrigation undertaken for approximately 6 hrs.
Wave 1	Golding	Gate 6.3 sump, Ch 101,800	14/03/2017	approx 400 kL	Nil	6.89	
Wave 1	Golding	Gate 6.3 sump, Ch 101,800	17/03/2017	approx 600 kL	Nil	6.7	
Wave 1	Golding	Gate 6.3 sump, Ch 101,800	26/03/2017	approx 600 kL	Nil	6.87	