

Water Discharge to Land Monitoring - July 2017

Monitoring Location: POINT 2 - Land Irrigation Areas

Wave/Portion	Contractor	Basin Name/ Number	Date of Discharge	Volume of Discharge (kL)	EPL water quality parameters		Comments
					Oil & Grease	pH	
Portion B	Davbridge	B10 South	5/07/2017	32	Nil	6.6	None
Portion B	Davbridge	B10 North	5/07/2017	30	Nil	6.6	None
Portion B	Davbridge	B10 South	16/07/2017	15	Nil	6.8	None
Portion B	Davbridge	B10 South	17/07/2017	15	Nil	6.87	None
Wave 1	Golding	Gate 6.3 table drain	1/07/2017	3	Nil	7.19	