

## Water Discharge to Land Monitoring - November 2017

Monitoring Location: POINT 2 - Land Irrigation Areas

Wave/Portion	Contractor	Basin Name/ Number	Date of Discharge	Volume of Discharge (kL)	EPL water quality parameters		Comments
					Oil & Grease	pH	
					Nil	6.5 – 8.5	
WBSR/Portion C	SEE Civil	Broadwater National Park	15/11/2017	200	Nil	7.59	Water irrigated in accordance with approved EWMS
WBSR/Portion C	SEE Civil	Broadwater National Park	16/11/2017	190	Nil	8.42	Water irrigated in accordance with approved EWMS
WBSR/Portion C	SEE Civil	Broadwater National Park	17/11/2017	210	Nil	7.78	Water irrigated in accordance with approved EWMS
A	SWC	TB 64530	3/11/2017	200	Nil	7.5	
A	SWC	Bostock Abutment	3/11/2017	400	Nil	7.2	
A	SWC	TB53660	6/11/2017	200	Nil	7.3	
A	SWC	TB53660	8/11/2017	60	Nil	7.2	
A	SWC	TB593580	9/11/2017	100	Nil	7	Lime added 9/11/2017. Alkalisied up from 5.0pH
Portion B	BMD	MCA01	14/11/2017	200	Nil	8.1	Water cart - dust supression
Portion B	BMD	MCA01	15/11/2017	100	Nil	8.03	Water cart - dust supression
Portion B	BMD	MCA01	17/11/2017	78	Nil	8.21	Water cart - dust supression
Portion B	BMD	MCA01	23/11/2017	80	Nil	8.03	Water cart - dust supression
Portion B	BMD	MC02	2/11/2017	Not provided	Nil	7.4	Water cart - dust supression
Portion B	BMD	MC01	23/11/2017	304	Nil	7.78	Water cart - dust supression
Portion B	BMD	MC01	20/11/2017	230	Nil	7.75	Water cart - dust supression
Portion B	BMD	MC01	17/11/2017	230	Nil	7.07	Water cart - dust supression
Portion B	BMD	IEB03	16/11/2017	20	Nil	6.53	Water cart - dust supression
Portion B	BMD	MC03	23/11/2017	290	Nil	7.2	Water cart - dust supression
Portion B, Section 6	Davbridge	B10 South	4/11/2017	30	Nil	6.77	
Portion B, Section 6	Davbridge	B10 North	6/11/2017	40	Nil	6.83	
Portion B, Section 6	Davbridge	B10 North	7/11/2017	40	Nil	6.7	
Portion B, Section 6	Davbridge	B10 south	8/11/2017	20	Nil	6.53	
Portion B, Section 6	Davbridge	B10 South	9/11/2017	30	Nil	6.81	