

## Sediment Basin Water Monitoring - September 2019

Monitoring Location: POINT 1 - Sediment Basin Outlet

Licensee: Laing O'Rourke Australia Construction Pty Ltd  
 Premises: Woolgoolga to Ballina Pacific Highway Upgrade Project, Harwood NSW 2465  
 Licence No: 20713



Portion / Section	Contractor	Basin Name/ Number	Rainfall start date	Rainfall end date	Rainfall total (mL)	Date of Treatment	Date of Discharge	Volume of Discharge (KL)	EPL water quality parameters				Comments
									Oil & Grease	pH	TSS	Turbidity	
									Nil	6.5 - 8.5	(mg/L)	NTU	
A S 4	BGC	SB 78400 E	31/08/2019	1/09/2019	0.0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Basin compliant with markers
A S 4	BGC	SB 78400 E	18/09/2019	19/09/2019	0.0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Basin compliant with markers
A S 4	BGC	SB 78400 E	27/09/2019	28/09/2019	0.0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Basin compliant with markers