Water Discharge to Land Monitoring - February 2018

Monitoring Location: POINT 2 - Land Irrigation Areas

				ļ	EPL water quality parameters		
Wave/Portion	Contractor	Basin Name/ Number	Date of Discharge	Volume of Discharge (kL)	Oil & Grease Nil	pH 6.5 – 8.5	Comments
Portion A	Construction	Culvert 134	1/02/2018	50	INII	8	
Portion A	Seymour Whyte Construction	Culvert 134	5/02/2018	200	Nil	7	
	Seymour Whyte						
Portion A	Construction	Culvert 144	5/02/2018	200	Nil	7.5	
	Seymour Whyte	Carvert	0/02/2010	200		7.0	
Portion A	Construction	Culvert 134	7/02/2018	50	Nil	7.1	
	Seymour Whyte				Nil		
Portion A Portion A	Construction	Culvert 134	8/02/2018	100	INII	7.2	
	Seymour Whyte				Nil		
	Construction Seymour Whyte	Culvert 134	6/02/2018	100		7.1	<u> </u>
Portion A	Construction	Culvert 134	9/02/2018	80	Nil	7	
	Seymour Whyte	Culvert 134	9/02/2016	00		'	
Portion A	Construction	Culvert 126	9/02/2018	30	Nil	n/a	Pumped into basin 52680
	Seymour Whyte		0,00,000				
Portion A	Construction	Culvert 134	12/02/2018	100	Nil	8.2	
	Seymour Whyte				Nil		
Portion A	Construction	Culvert 141	20/02/2018	50	INII	6.9	
Portion A	Seymour Whyte Construction	Out out 404	04/00/0040	100	Nil	0.0	
	Seymour Whyte	Culvert 134	21/02/2018	100		8.2	
Portion A	Construction	Drain	22/02/2018	50	Nil	7	
	Conduction						
Portion A S3 & 4	BMD	N/A, water ponding at A21	7/02/2018	10	Nil	7.1	Nil basins within work areas.
		N/A, water ponding at A21	6/02/2018	10	Nil	6.75	Nil basins within work areas.
Portion A S3 & 4	BMD	TV/Y, Water portaing at 712 i	0/02/2010	10	1411	0.70	THI BUSINS WITHIN WORK GICUS.
Portion A S3 & 4	BMD	N/A, water ponding at A21	5/02/2018	40	Nil	6.6	Nil basins within work areas.
FUILIUII A 33 & 4	DIVID	· · · · ·					+
Portion A S3 & 4	BMD	N/A, water ponding at A21	5/02/2018	0.3	Nil	7.9	Nil basins within work areas.
Portion D	LendLease	Monti's Basin	6/02/2018	-	Nil	6.83	Water pumped into water cart
Portion D	LendLease	Lumleys Hill Basin	6/02/2018	-	Nil	7.21	Water pumped into water cart
Portion D	LendLease	Cut 1 Basin	8/02/2018	-	Nil	6.92	Water pumped into water cart
Portion D	LendLease	Cut 3 Basin	9/02/2018	-	Nil	7.7	Water pumped into water cart
Portion D	LendLease	Wardell Road Basin	9/02/2018	-	Nil	7.03	Water pumped into water cart
Portion D S10	Quickway	D05	21/02/2018	5	Nil	7.2	11.52 Tubidity result permit no: 001
Portion C	СРВ	Irrigation Basin #1	27/12/2017	10	Nil	7.4	, , , , , , , , , , , , , , , , , , , ,
Portion C	СРВ	Irrigation Basin #2	28/12/2017	8	Nil	7.4	
Portion C	СРВ	Irrigation Basin #1	8/01/2018	10	Nil	7.4	<u> </u>
POLIIOII C	UFB	imgation basin #1	0/01/2010	10	INII	1.4	